BLAKELY SOKOLOFF TAYLOR ZAFMAN

A LIMITED LIABILITY PARTNERSHIP INCLUDING LAW CORPORATIONS

TELEPHONE (408) 720-8300

BSTZ_MAIL@BSTZ.COM

www.bstz.com

INTELLECTUAL PROPERTY LAW

SILICON VALLEY

1279 OAKMEAD PARKWAY SUNNYVALE, CALIFORNIA 94085-4040 OTHER OFFICES

AUSTIN, TX

SILICON VALLEY/SAN JOSE, CA LOS ANGELES, CA ORANGE COUNTY/COSTA MESA, CA PORTLAND/LAKE OSWEGO, OR SEATTLE, WA DENVER, CO

April 14, 2004

Commissioner for Patents PO Box 1450 Alexandria, VA 22313-1450

Re: **CERTIFICATE OF CORRECTION** U. S. Letters Patent No. 6,717,823

Issued: April 6, 2004

For: SYSTEMS HAVING MODULES WITH

BUFFER CHIPS Inventor: McCall et al. Our File No. 42390.P11992 Certificate

APR 2 8 2004

of Correction

Dear Sir:

Enclosed is the Certificate of Correction (two copies) for the above-referenced patent.
This request for correction is made under rule 322 of the Rules of Practice and 35 U.S.C.
Section 254.

Respectfully submitted,

BLAKELY, SOKOLOFF, TAYLOR & ZAFMAN LLP

Edwin H. Taylor Reg. No. 25,129

EHT/jsq Enclosures

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,717,823

DATED : April 6, 2004

INVENTOR(S) : McCall et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 7, at line 7, delete "I6" and insert -- I16--.

In column 7, at line 25, delete "17" and insert -- I7--.

In column 7, at line 26, delete "115" and insert -- I15--.

In column 7, at line 59, delete "C11" and insert --CI1--.

In column 7, at line 62, delete "C19" and insert --CI9--.

In column 10, at line 35, delete "I0" and insert -- I10--.

In column 10, at line 64, delete "I0" and insert -- I10--.

In column 11, at line 50, delete "PI" and insert --P1--.

In column 14, at line 36, delete "I6" and insert -- I16--.

In column 19, at the beginning of line 29, delete "A".

MAILING ADDRESS OF SENDER
BLAKELY, SOKOLOFF, TAYLOR & ZAFMAN
12400 Wilshire Blvd. 7th floor
Los Angeles, CA 90025-1026

PATENT NO. <u>6,717,823</u>

Certificate of Correction (PTO Form 1050)-Amended

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,717,823

DATED : April 6, 2004

INVENTOR(S) : McCall et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 7, at line 7, delete "I6" and insert -- I16--.

In column 7, at line 25, delete "17" and insert -- I7--.

In column 7, at line 26, delete "115" and insert -- I15--.

In column 7, at line 59, delete "C11" and insert --CI1--.

In column 7, at line 62, delete "C19" and insert --CI9--.

In column 10, at line 35, delete "I0" and insert -- I10--.

In column 10, at line 64, delete "I0" and insert -- I10--.

In column 11, at line 50, delete "PI" and insert --P1--.

In column 14, at line 36, delete "I6" and insert -- I16--.

In column 19, at the beginning of line 29, delete "A".

MAILING ADDRESS OF SENDER
BLAKELY, SOKOLOFF, TAYLOR & ZAFMAN
12400 Wilshire Blvd. 7th floor
Los Angeles, CA 90025-1026

PATENT NO. 6,717,823

Certificate of Correction (PTO Form 1050)-Amended